FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Englneer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

		SHIJUKUMBR.00.
1.	Name of the Officer	May Baselions Eglish Hedium School
2.	Name of the School	
3. _.	Location with name of Education District/ Sub. District	Kutamale. Amboor, Negyatistans
4.	Classification of Building as specified in column 4 of the application for fitness certificate and size.	1. Caf 58-10 x 8-05 x 3-60m (RCC) FF 58-10 x 8-05 x 3-60m (RCC) SF 28-70 x 8-05 x 3-60m (Sleet)
	•	
5.	Period for which the certificate is issued	2023-2021
6.	Nature of defects, if any	
	a) Foundation and basement	
	b) Superstructure	
	c) Doors and Windows	
	d) Wood work wrought and put up) NIC
	e) Roof	
	f) Flooring	
	g) Miscellaneous (Cracks, etc.)	
7.	Any major defects noticed which will render the building unsafe in any manner	No
8.	Whether maintenance works have been done properly	yes, the standare is sound see under normal wealth condition
9.	Whether the structure is sound or not for conducting class Note: 1. The stability of the structure should be examined exposure of flood etc. 2. Any additional observations is separately with this certificate.	d also with reference to location, altitude, intensity of wind, if deemed necessary for the certificate may be furnished
	CERTI	FICATE
		24/20/2020
	certified that the school building was inspected by	me on 26/05/2023 and
fou	and to be fit /unfit to conduct classes, for the period	2023 - 2024 for the
rea	sons stated above.	
	CE OF THE	
С,	Ombooxi Late Vo	8
rla -	te: 26/5/2023.	A service of the serv
Dat	te:KOJ.S.JOQUANS	Assistant Engineer LSGD Section

····Amboori Grama Panchayath.... Assistant Engineer